## Woodbine Tot Lot: 1509 Woodbine Street Improvement Recommendations

Update park signage Add a gate to the alley The existing park welcome sign will be Community feedback indicated that families updated to the current standard. along Dogwood Drive would like to access the park through the alley. Along with a gate, additional signage in the alley would need to Add additional seating be installed warning drivers that children are Install picnic table seating that could be used present. as a gathering area for caregivers and for multi-generational gatherings. Also install multi-tiered seating near the playground that Add paint/thermoplastic to the alley can be used as a gathering area for caregivers To add additional color and visibility to the and allows them to see children throughout alley near the playground, install a the playground. thermoplastic or painted design in the alley along the length of the playground. This acts Renovate and reconfigure the playground as a safety feature to help cars slow down and The existing playground is outdated and does adds color and vibrancy to the park. not meet the community needs. It can be difficult for caregivers to see children throughout the playground due to the location of the equipment. The play equipment will be updated with new structures for multiple age groups. Park Boundary 15 30 60 Feet